


VISUAL INSPECTION

A-17

Rear tang not
flush with the
stock.



Stock rein-
forcement pins
are egg shaped

