


VISUAL INSPECTION

A-23

mark on
rein-
forcement pin.



Lack of stain

