

VISUAL INSPECTIONS

Rear Tang
Not Flush
with the Stock.



Stock Rein-
forcement Pins
Are Egg Shaped.

