

REMINGTON GUN REPAIR SURVEY  
 REMINGTON GUN REPAIR TALLY FORM

SHOP NAME GUNATORIUMGUNSMITH Mike SullivanADDRESS 5323 N ARGONNE SPOKANE WA. 99206

| DATE     | MODEL     | SERIAL NO.                          | REPAIR MADE                   |
|----------|-----------|-------------------------------------|-------------------------------|
| 7/5/82   | 700       | B6244847                            | SALTS IN EJECTOR              |
| 10/9/82  | 760       | D7172875                            | Weak action Bar lock spring   |
| 10/21/82 | 700       | A6882587 <sup>PA</sup>              | STOCK CRACKED                 |
| 1/6/83   | 700       | B6224986 <sup>PA</sup>              | STOCK CRACKED                 |
| 1/11/83  | 760       | D7233835 <sup>PA</sup>              | Lubed grease in fire pin      |
| 1/25/83  | 1100 LT20 | N560707K <sup>AB</sup>              | Broken action Bar spring      |
| 3/18/83  | 820       | V329341V <sup>KO</sup>              | Broken stock                  |
| 3/21/83  | 700 BDL   | A6663337 <sup>EO</sup>              | " "                           |
| 3/30/83  | 700 BDL   | B6368217 <sup>AS</sup>              | Misfire Check Test fire       |
| 4/11/83  | 7         | 7601744 <sup>BD</sup>               | Triggers (updating)           |
| 4/22/83  | 7         | 7604686 <sup>SA</sup>               | TRIGGER (updating)            |
| 7/14/83  | 870       | V620249M <sup>SB</sup>              | shell latch R.H.              |
| 8/15/83  | 700       | 6517709 <sup>AB</sup>               | fire solenoid released        |
| 8/18/83  | 700       | <del>A6</del> B6236520 <sup>3</sup> | " "                           |
| 8/17/83  | 870       | V114637X <sup>RO</sup>              | LH shell latch Broken         |
| 8/22/83  | 9200      | OV47199 <sup>BO</sup>               | ADJUST TRIGGER SCREW          |
| 9/7/83   | 870       | V552862M                            | ejector come off              |
| 7/15/83  | 870       | V798422M <sup>XB</sup>              | STOCK CRACKED                 |
| 9/10/83  | 870       | V943699V <sup>PD</sup>              | Block pin, fell out (Locking) |
| 11/14/83 | 74        | A4042406 <sup>RO</sup>              | Work done on shell mechanism  |
| 11/15/83 | 742       | A7305694X1                          | Ejector defective             |
| 11/16/83 | 1100 LT20 | N627571K                            | BURR IN CHAMBER               |