

A
L

MODEL 700 PROBLEM

A Small quantity of Model 700, 7 and 40X rifles may have been made with an out of specification part. The sear safety cam in a limited quantity of rifles made between January 10 and March 6 may have been softer than our specification. This "soft" part may show premature wear and may eventually cause harder than normal safety switch forces.

Remington has checked the guns in our inventory and is taking steps to check all guns that were shipped. Teams of employees have been dispatched to the field to check and repair, if necessary, guns at our major accounts. Since the rifles in question were made quite recently, we feel that this will be effective in achieving the repairs of all rifles that may be involved.



AL 002446Z

H