Scrubber on the any of the synthetic M710 parts, especially the bolt stop. A chemical reaction can occur, and the parts will crack.

