	D	I E ™
306	EJECTOR DOES NOT HAVE ENOUGH TENSION	X
307	EJECTOR STUCK IN BOLT	x
308	FREEBORE MISCUT / MIN	×
309	SCOPE MOUNT THREADS UPSET IN RECEIVER	×
310	CLOSES HARD OVER SHELL	- X
311	BARREL BRACKET OUT OF POSITION	× 1
312	BOLT STOP STICKS	X
313	ISS BOLT LOCKED IN THE "OPEN" POSITION	. X
314	RETURNED FOR RECALL/UPDATE	X
	STOCK NOT BEDDED PROPERLY	×
	TRIG ADJ SCREWS RESET, CANNOT READJUST	X
317		INDUNENCATATO
318		700 E.TRON
	ACCURACY	×
	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPAIR	×
	BUTT PLATE / RECOIL PAD IS BROKEN	X
	CHAMBER ROUGH / RINGS / TEARS / TIGHT	×
	CONSIGNED GUN	X
	COULD NOT DUPLICATE CUSTOMERS COMPLAINT CREDIT RETURN	X
		× X
	DAMAGE APPEARS TO HAVE OCCURRED IN TRAN部	×
	DAMAGES CASES, BULLETS OR SHELLS	X
	FAILS TO FIRE	X
	FINISH IS DAMAGED ON TRIGGER GUARD/PLATE	X
	HEADSPACE IS EXCESSIVE MUZZLE DAMAGE	X
	NO CORRESPONDENCE	X
	NO FAULT FOUND AT BENCH	X
	PACKING ERROR	×
	POOR FINISH - BARREL	x
	POOR FINISH - FORE END	×
	POOR FINISH - RECEIVER (OR FRAME)	x l
	POOR FINISH - STOCK	x
*************	RECEIVER IS MISCUT	x l
	RUSTED COMPONENT	×
	SAFETY CONCERN, EXAMINED BY PRODUCT SERVICE	×
	SIGHTS OFF CENTER	x
	STOCK CRACKED	x
	STOCK MARRED	x
	TRIGGER PULL IS OUT OF FACTORY SPECS.	×
	CHAMBER DIRTY / RUSTY	×
	FAILS TO EXTRACT	X
	HEADSPACE AT MINIMUM	×
210	DITUNO CALTO ADE DI ESEDINO EPOMARMENALI	×
350	EXTRACTOR MISSING	x
1001	I MOLI I WINGSMALINE TOMOGRAMMAN.	х
352	TRIGGER CONNECTOR BINDS	X
353	EXTRACTOR IS BROKEN	×
354	FAILS TO EJECT	×
	WILL NOT FEED PROPERLY	×
	RIFLING ROUGH / MISCUT / DAMAGED	X
	ACTION IS DIFFICULT TO OPEN	x
358	EXTRACTOR IS CATCHING ON SHELL HEAD	х
	MAGAZINE DIFFICULT TO LOAD	×
360	POOR RECOIL PAD TO STOCK FIT	x
361	ROLL MARKING VISIBLE INSIDE BORE	×
	BOLT HANDLE FELL OFF. BOLT IS BROKEN	×
	RECEIVER PLUG SCREWS BROKEN	x
	RECEIVER SCOPE MOUNT HOLES OFF CENTER	X
	BOLT: #ACE / SHROUD DAMAGED	X
366	BORE S HEAT CHECKED	X
	ANNANA 2006000	