		dita.	Me
	D	E	
	TRIGGER PULL IS OUT OF FACTORY SPECS.	X	
	CHAMBER DIRTY / RUSTY	× 	
	FAILS TO EXTRACT HEADSPACE AT MINIMUM		
	BLUING SALTS ARE BLEEDING FROM METAL	100 (n. 1996) 100 (n. 1996)	× .
	EXTRACTOR MISSING	x	
	FAULTY MAGAZINE	x	
	TRIGGER CONNECTOR BINDS	X	¥
925	EXTRACTOR IS BROKEN		
926	FAILS TO EJECT	×******	
927	WILL NOT FEED PROPERLY	x X	
928	ACTION IS DIFFICULT TO OPEN	X	
	EXTRACTOR IS CATCHING ON SHELL HEAD	X	
	MAGAZINE DIFFICULT TO LOAD	×	
	POOR RECOIL PAD TO STOCK FIT	X	
		X	
	BOLT HANDLE FELL OFF, BOLT IS BROKEN	X	
	FORE END CRACKED	×	
	FORE END FIT IS TOO TIGHT FORE END IS TOO LOOSE	X	
	FORE END IS TOO LOOSE	× ×	
	GRIP CAP IS DAMAGED	x	
		× x	
	EJECTOR BROKEN	x X	
	CHOKE TUBE CONCENTRICITY	x	
942	CHOKE TUBE CRACKED	х	
943	CHOKE TUBE THREADS ARE DAMAGED	Х	
944	FIRING PIN HITS PRIMER OFF CENTER	Х	
	RECEIVER - EJECTOR IS LOOSE	Х	
	RIB DOESN'T ALIGN WITH RECEIVER	Х	
	RIB IS DAMAGED	X	
********	RIB LANDS ARE LOOSE	X	
	RIB SWEEPS TO THE LEFT RIB SWEEPS TO THE RIGHT	×	
	BARREL TO RECEIVER MISALIGNMENT	x	
	BOLT - EXTRACTOR HITS INSIDE CHAMBER	x	
	BURR AT RIM AREA OF CHAMBER	x	
	CARRIER OUT OF ADJUSTMENT	x	
	GAS ORIFICE HOLE IS OVERSIZE	х	
956	MAGAZINE TUBE SEPARATED FROM RECEIVER	х	
957	3 SHOT PLUG AT WRONG END OF MAG TUBE	х	
	ACTION SPRING TUBE FELL OFF	Х	
	BARREL GUIDE STUD MISSING	Х	
	BARREL SUPPORT SEPARATED FROM MAG TUBE	X	
		X	
	GAS CYLINDER SEPARATED FROM BARREL GAS HOLES OUT OF POSITION	×	
	GAS HOLES OUT OF POSITION TRIGGER - CARRIER LATCH TAB IS OUT OF ADJUSTMENT	×	
	INTERCEPTOR LATCH STUD MISSING	×	
	CARDBOARD PACKING RING WAS NOT REMOVED	x	
	PISTON/PISTON SEAL INCORRECTLY INSTALLED	x	
	RECEIVER FEED CUTS ARE ROUGH	x	
969			
970	MALFUNCTIONS MO	DELS	
	ACCURACY	Х	
	BALANCE OF FIREARM IS NEEDED TO PERFORM PROPER REPA	AIR X	
	BUTT PLATE / RECOIL RAD IS BROKEN	X	
	CHAMBER ROUGH / RINGS / TEARS / TIGHT	X	
		X	
9/6	COULD NOT DUPLICATE CUSTOMERS COMPLAINT	X	
_			

Subject to Protective Order Williams v. Remington