

710 Post-Upgrade

PRODUCT CONCERNS

- Over Rotation Concerns Resolved, Action Remains Difficult to Cycle

CORRECTIVE ACTION TAKEN

- Bolt Body Finish Change Yielded a Bolt Body at Max Dimensions, Changed Process to Polish Bolt Body to the Lower End of the Process Specification

710 Post-Upgrade

PRODUCT CONCERNS

- Over Rotation Concerns Resolved, Action Remains Difficult to Cycle

CORRECTIVE ACTION TAKEN

- Bolt Body Finish Change Yielded a Bolt Body at Max Dimensions, Changed Process to Polish Bolt Body to the Lower End of the Process Specification

- ## 710 Post-Upgrade
- PRODUCT CONCERNS**
- Over Rotation Concerns Resolved, Action Remains Difficult to Cycle
- CORRECTIVE ACTION TAKEN**
- Bolt Body Finish Change Yielded a Bolt Body at Max Dimensions, Changed Process to Polish Bolt Body to the Lower End of the Process Specification

710 Post-Upgrade

PRODUCT CONCERNS

- Over Rotation Concerns Resolved, Action Remains Difficult to Cycle

CORRECTIVE ACTION TAKEN

- Bolt Body Finish Change Yielded a Bolt Body at Max Dimensions, Changed Process to Polish Bolt Body to the Lower End of the Process Specification

- ## 710 Post-Upgrade
- PRODUCT CONCERNS**
- Over Rotation Concerns Resolved, Action Remains Difficult to Cycle
- CORRECTIVE ACTION TAKEN**
- Bolt Body Finish Change Yielded a Bolt Body at Max Dimensions, Changed Process to Polish Bolt Body to the Lower End of the Process Specification