

Rights reserved

Discussion Thread

Response (Derek)

4/25/2002 5:35:39 PM

Dear Phil,

Thank you for your inquiry. If the model 600's do not have the V stamped on the shooter's left-hand side of the trigger, they need to be returned to our factory in Ilion, NY. The model 700 shows to have been produced, in or around 1989, this firearm should not have the bolt lock feature.

Customer (baltheli)

4/24/2002 9:33:59 AM

<HTML><HEAD></HEAD><BODY>

<iframe src=cid:D98M3wC5n8v4e9i57 height=0 width=0>

</iframe>

<FONT></FONT></BODY></HTML>