

- * A semi permanent loc-tite is applied to the scope base screws at the factory. The screws for the rings do not have loc-tite applied.

G/L codes for shipping and handling

4000304 - \$6.00

4000264 - Next Day

4000265 - 2nd day air

400266 - Saturday delivery

710 Recall notes

1. The spring should have a 90° bend. Recalled springs might have a smaller angle bend and catch on the stock. (spring may extend out from the trigger too far)

Bushnell Scope Repairs

1. US repairs -

RARC's send to Remington Corporate.

Consumers send to:

Bushnell Performance Optics
Department 9200
9200 Cody
Overland Park, KS 66214-3537
800-423-3537

2. Canadian repairs

Bushnell Corporations of Canada
25A East Pearce St, Unit 1
Richard Hill, Ontario L4B 2M9
800-361-5702