

21072	\$14.00	7	150503	
21072	\$14.00	3	150561	
21072	\$14.00	1	150739	
21072	\$14.00	5	150737	
21072	\$14.00	5	150736	
21060	\$30.25	9	SH4823	
21060	\$44.50	16	SH4799	
21060	\$44.50	10	SH4818	
21060	\$44.50	15	SH4805	
21060	\$44.50	8	SH4827	
21060	\$24.50	81	SH4631	
21060	\$24.50	100	SH4557	
107773	\$15.00	1	DK1243	
107773	\$15.00	1	DK1244	
107773	\$15.00	1	DK1245	
107773	\$15.00	1	DK1246	
107773	\$15.00	1	DK1247	
107773	\$15.00	1	DK1248	
107773	\$15.00	1	DK1249	
107773	\$15.00	1	DK1250	
107773	\$15.00	1	DK1251	
20616	\$14.00	9	152326	
20616	\$19.61	9	153028	
20616	\$19.00	1	124239	
20616	\$41.87	1	131486	
20616	\$19.61	35	153113	
21047	\$29.95	15	143763	
21047	\$35.44	19	128431	
21047	\$30.74	8	128430	
21047	\$29.95	2	128429	
21047	\$29.95	6	128428	
20017	\$34.20	1	149643	
20017	\$33.74	12	149614	
20017	\$33.50	8	149613	
20017	\$33.74	12	149616	

KY	710	999999	-	M5	UPDATED.
KY	710	7103170	-	UPDATE	UPDATED.
KY	710	999999	-	M5	UPDATED.
KY	710	999999	-	MAG RELEASE BUTTON	UPDATED.
KY	710	71023204	07-01	M5	UPDATED. REAR TAKEDOWN SCREW MISSING.
OH	710	71031180	09-01	CROSSHAIRS BROKE ON SCOPE.	REPLACED SCOPE.
OH	710	71007402	02-01	CHAMBER	RETURNED TO FACTORY FOR REPAIR, RETURNED TO CUSTOMER.
OH	710	71025530	08-01	DOES NOT LOCK.	RETURNED TO FACTORY FOR REPAIR, RETURNED TO CUSTOMER.
OH	710	71029484	09-01	REPAIR AND RETURN.	RETURNED TO FACTORY FOR REPAIR, RETURNED TO CUSTOMER.
OH	710	71033111	10-01	CLIP.	RETURNED TO FACTORY FOR REPAIR, RETURNED TO CUSTOMER.
OH	710	71003960	01-01	TRIGGER DOESN'T WORK, BENT	RETURNED TO PADUCAH.
OH	710	71016931	05-01	SCOPE RING RUBBER FELL OUT	RETURNED TO PADUCAH.
MS	710	71002753	12-00	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71008025	03-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71008245	03-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71009128	03-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71010275	03-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71010313	03-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71017674	05-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71034968	10-01	WHSE INSPECTION.	WHSE INSPECTION.
MS	710	71034974	10-01	WHSE INSPECTION.	WHSE INSPECTION.
WI	710	71020063	06-01	M33	REPLACED WITH STORE STOCK.
WI	710	71008564	03-01	M5	MAILED TO PADUCAH FOR WARRANTY.
WI	710	71022124	06-01	M1	REMOUNTED SCOPE MOUNTS AND BORESIGHTED SCOPE.
WI	710	71024675	07-01	EXTRACT.	REPLACED EXTRACTOR AND TEST FIRED.
WI	710	71022203	06-01	TRIGGER GUARD BROKEN.	RETURNED TO REMINGTON FOR EXCHANGE.
OK	710	71004092	01-01	BOLT STOP BROKEN.	SENT TO PADUCAH FOR REPAIRS.
OK	710	71004309	01-01	BOLT HANDLE SEPERATED.	SENT TO PADUCAH.
OK	710	71003868	01-01	BOLT HARD TO OPERATE.	SENT TO PADUCAH.
OK	710	71033789	10-01	DEFECTIVE MAGAZINE LATCH.	SENT TO PADUCAH.
OK	710	71037188	11-01	SYSTEM ON.	SENT TO PADUCAH.
IMN	710	71004034	01-01	MAG RELEASE LEVER BROKE.	SENT TO PADUCAH.
IMN	710	71001651	01-01	BOLT STOP.	SENT TO PADUCAH.
IMN	710	71003820	01-01	BOLT LATCH NOT WORKING.	SENT TO PADUCAH.
IMN	710	71010362	03-01	M5	SENT TO PADUCAH.

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0008972

MAE00008888