

REPAIRED BOLT RETAINER TO HOLD BOLT HANDLE IN PLACE, INSTALLED NEW BOLT HANDLE AND TEST	20017	\$46.72	1	149572
ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, FREED UP STICKY LINKAGE IN TRIGGER GROUP AND	20017	\$48.01	1	149573
POLISHED CHAMBER, ADJUSTED EJECTOR, BOLT & HAMMER FROM BINDING AND TEST FIRED.	20017	\$47.18	1	149568
ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, SMOOTHED BOLT TRAVEL AND TEST FIRED.	20017	\$47.01	3	149574
ADJUSTED EJECTOR, SMOOTHED ROUGH EDGES ON BOTTOM OF BOLT AND TEST FIRED.	20017	\$46.94	1	149570
INSTALLED & FIT EXTRACTOR ASSY CORRECTLY, ADJUSTED BOLT HAMMER AND TEST FIRED.	20017	\$45.70	3	149569
POLISHED CHAMBER, ADJUSTED EJECTOR, SMOOTHED BOTTOM OF BOLT AND TEST FIRED.	20017	\$47.90	6	149571
REPLACED EXTRACTOR.	20954	\$33.86	3	153551
REFIT EXTRACTOR AND TESTED.	20954	\$26.00	17	151898
REPAIRED LINKAGE IN TRIGGER ASSY TO OPERATE SMOOTHLY, ADJUSTED EJECTOR TO ENGAGE SHELLS	20017	\$47.27	1	149679
ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, ADJUSTED CLIP LATCH SPRING TENSION AND TEST	20017	\$41.51	1	149681
REPAIRED SAFETY & PLONGER TO OPERATE SMOOTHLY AND TEST FIRED.	20017	\$43.38	1	149677
REDRILLED & TAPPED RECEIVER & REM BOLT TO ACCEPT 8-40 SCREWS AND SUPPLIED REM. BASE TO	20017	\$50.64	1	149682
REPLACED WEAR BOLT HANDLE, ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER AND TEST FIRED.	20017	\$48.10	1	149575
ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER, ADJUSTED CLIP LATCH TO HOLD CLIP IN PLACE AND	20017	\$42.69	1	149680
ADJUSTED EJECTOR AND TEST FIRED.	20017	\$39.40	1	149678
REPAIRED TRIGGER TO ENGAGE DEEPER AND TEST FIRED.	20017	\$41.40	3	149676
REPAIRED TRIGGER LINKAGE TO OPERATE SMOOTHLY, ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER	20017	\$44.14	1	149675
ADJUSTED EJECTOR TO ENGAGE SHELLS DEEPER AND TEST FIRED.	20017	\$41.64	1	149674
DECRASED EXTRACTOR SPRING & PLONGER, ADJUSTED EXTRACTOR TO GRAB RIM OF SHELL	20017	\$44.76	1	149673
REPLACED EXTRACTOR, SPRING & PLONGER AND TEST FIRED.	20017	\$47.95	1	149672
REPLACED & FIT NEW BOLT RETAINING PIN SPRING, ADJUSTED EJECTOR TO CATCH SHELLS DEEPER AND	20017	\$48.23	1	149579
REPLACED DEFECTIVE MAGAZINE AND TEST FIRED.	20017	\$35.63	3	149578
REPLACED & FIT BROKEN BOLT HANDLE.	20017	\$30.57	2	149577
ADJUSTED TRIGGER GROUP TO OPERATE CORRECTLY, ADJUSTED EJECTOR TO ENGAGE SHELLS	20017	\$51.47	1	149576
REPLACED HAMMER & TWO NEW MAGAZINES. ADJUSTED EJECTOR, FREED UP LINKAGE IN TRIGGER	20954	\$62.27	2	153553
ASSY AND TEST FIRED.	20017	\$45.01	1	149725
ADJUSTED BOLT HANDLE RETAINING SPRING & EJECTOR AND TEST FIRED.	20017	\$44.01	2	149726
DECRASED EDGE OF CHAMBER, ADJUSTED EJECTOR AND TEST FIRED.	20017	\$32.50	1	149728
REPAIRED LINKAGE IN TRIGGER GROUP FROM STICKING, ADJUSTED EJECTOR TO ENGAGE SHELLS	20017	\$47.38	1	149729
REPAIRED EJECTOR TO ENGAGE SHELLS DEEPER, ADJUSTED CLIP LATCH TO HOLD CLIP IN PLACE AND	20017	\$45.38	1	149730
ADJUSTED EJECTOR AND TEST FIRED.	20017	\$41.75	1	149727
POLISHED CHAMBER, REFIT EXTRACTOR AND TESTED.	20954	\$30.50	7	153425