

KY	710	71004530	01-01	DEFECTIVE MAG.	REPLACED MAG.	21072	\$14.00	1 150478
KY	710	71003398	01-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	1 150575
KY	710	71004842	01-01	BAD BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	1 150574
KY	710	71003829	01-01	BAD BOLT STOP.	UPDATED.	21072	\$14.00	2 150572
KY	710	71001651	01-01	BOLT STOP BAD.	REPLACED BOLT STOP.	21072	\$14.00	3 150567
KY	710	71003782	01-01	UPDATE.	UPDATED.	21072	\$14.00	3 150566
KY	710	71003813	01-01	UPDATE, BOLT STOP WORN, MAG FELL APART.	UPDATED, REPLACE MAG.	21072	\$14.00	5 150735
OH	710	71003960	01-01	TRIGGER DOESN'T WORK, BENT.	RETURNED TO PADUCAH.	21060	\$24.50	61 SH4631
OK	710	71004309	01-01	BOLT HANDLE SEPERATED.	SENT TO PADUCAH.	21047	\$35.44	19 128431
OK	710	71003668	01-01	BOLT HARD TO OPERATE.	SENT TO PADUCAH.	21047	\$30.74	6 128430
OK	710	71004092	01-01	BOLT STOP BROKEN.	SENT TO PADUCAH FOR REPAIRS.	21047	\$29.95	15 143763
MN	710	71004034	01-01	MAG RELEASE LEVER BROKE.	SENT TO PADUCAH.	20017	\$34.20	1 149643
MN	710	71001651	01-01	BOLT STOP.	SENT TO PADUCAH.	20017	\$33.74	12 149614
MN	710	71003820	01-01	BOLT LATCH NOT WORKING.	SENT TO PADUCAH.	20017	\$33.50	8 149613
AL	710	71004085	01-01	RETURNED TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 138651
CT	710	71003825	01-01	FORWARD TO PADUCAH.	FORWARDED TO PADUCAH.	20629	\$10.82	1 151131
KY	710	71003655	01-01	STIFF BOLT.	REPLACED BOLT BODY.	21072	\$14.00	5 157552
KY	710	71001106	01-01	EJECTOR STUCK.	CLEANED AND TESTED.	21072	\$14.00	1 157589
KY	710	71004085	01-01	NOT EJECTING.	TESTED EJECTOR, OK, TEST FIRED.	21072	\$16.25	1 157657

Subject to Protective Order - Williams v. Remington