

MN	710	71010382	03-01	M5	SENT TO PADUCAH.	20017	\$33.74	12 149618
CA	710	71003412	03-01	BOLT BROKEN.	SENT TO FACTORY.	20106	\$34.29	11 149400
CA	710	71010145	03-01	M5	GUN SENT TO FACTORY, FACTORY REPAIRED BOLT	20106	\$30.29	1 149391
CAN	710	71007679	03-01	NOT EXTRACTING AMMO	REPLACED EXTRACTOR, POLISHED CHAMBER, TESTED, RETURNED TO FACTORY FOR	20630	\$68.40	11 30966
MI	710	71010334	03-01		WARRANTY REPAIR.	21019	\$22.00	18 141759
OR	710	71010563	03-01	MAG RELEASE BROKEN.	SHIPPED TO PADUCAH.	20023	\$21.63	1 110539
KY	710	71010334	03-01	PLASTIC SHROUD SHATTERED ON FIRING PIN ASSY.	REPLACED FIRING PIN ASSY.	21072	\$14.00	5 124098
KY	710	71009135	03-01	MAG LATCH BROKEN.		21072	\$14.00	1 157665
KY	710	71008360	03-01	TRIGGER WORKS INTERMITTENT AND SAFETY WORKS HARD.	REPLACED REC INSERT ASSY.	21072	\$14.00	11 124066
KY	710	71009041	03-01	CROSSHAIRS IN SOCPE ARE TILTED.		21072	\$14.00	8 150039
KY	710	71008596	03-01	BOLT WILL NOT HOLD NEW EXTRACTOR.	POLISHED CHAMBER, RUST IN CHAMBER AND BAD BOLT STOP	21072	\$16.25	8 150038
KY	710	71008092	03-01		REPLACED BOLT STOP.	21072	\$14.00	1 124077
KY	710	71010151	03-01	M5		21072	\$14.00	2 124078
KY	710	71010145	03-01	M5		21072	\$17.50	1 124043
KY	710	71010262	03-01	M5		21072	\$17.50	11 150593
KY	710	71010903	03-01	NOT FEEDING.	MAD SURE MAG LATCH PROPERLY INSTALLED AND	21072	\$14.00	7 157559
KY	710	71008706	03-01	BOLT HEAD BURRED.	REPLACED MAG SPRING.	21072	\$17.50	1 157581
KY	710	71013355	04-01	HARD TO CHAMBER RD.	NEW BOLT HEAD AND TESTED.	21072	\$14.00	3 150622
KY	710	71013304	04-01	M8	NEW BOLT HEAD.	21072	\$19.00	3 150623

Subject to Protective Order - Williams v. Remington