

OK	710	71033844	10-01	BOLT LOCKS UP.	SENT TO PADUCAH.	21047	\$30.74	8 143549
OK	710	71033585	10-01	BOLT LOCKS UP, BOLT HITS FIRING PIN OUT OF SAFETY.	SENT TO PADUCAH.	21047	\$30.44	12 143548
OK	710	71032297	10-01	BOLT HANDLE FELL OFF.	SENT TO PADUCAH.	21047	\$35.44	7 143547
OK	710	71032507	10-01	CROSS HAIRS OFF CENTER.	SENT TO PADUCAH.	21047	\$30.07	7 143545
KY	710	71035317	10-01	MAG LATCH BROKEN	REPLACED MAG LATCH.	21072	\$18.00	4 150540
KY	710	71034636	10-01	CUSTOMER REQUESTED FUNCTION & SAFETY TEST.	TESTED PER CUSTOMER REQUEST.	21072	\$14.00	4 124004
KY	710	71033111	10-01	WON'T FEED FROM MAG.	TESTED WITH NO PROBLEM.	21072	\$14.00	1 124032
KY	710	71034348	10-01	PLASTICK SHROUD ON BACK OF FIRING PIN BROKEN.	REPLACED FIRING PIN.	21072	\$14.00	3 150558
KY	710	71034441	10-01	JAMS UP.	DRESSED DOWN BURR & BOLT HEAD, RETESTED, COULD NOT	21072	\$14.00	4 150455
KY	710	71032739	10-01	MAG LATCH BROKE.	REPLACED MAG LATCH	21072	\$14.00	2 150465
KY	710	71033023	10-01		REPLACED FIRING PIN ASSY & TEST FIRED.	21072	\$16.25	7 150487
KY	710	71032801	10-01	M5	UPDATED.	21072	\$14.00	7 150529
KY	710	71033844	10-01	STICKING WHEN PULLIN BOLT BACK.	REMOVED BURR FROM BOLT HEAD.	21072	\$14.00	7 150527
KY	710	71033699	10-01	M5	UPDATED.	21072	\$14.00	7 150524
KY	710	71032507	10-01		REPLACED SCOPE.	21072	\$14.00	7 150523
KY	710	71033585	10-01		REPLACED FIRING PIN MECHANISM.	21072	\$14.00	7 150522
KY	710	71032297	10-01	M5	UPDATED.	21072	\$14.00	7 150519
KY	710	71033004	10-01	NOT NOTE ENCLOSED.	TESTED, CHECKED ALL SAFETIES, OVERALL FUNCTION	21072	\$14.00	7 150517
KY	710	71033969	10-01		REPLACED BOLT STOP & ADJUSTED BOLT STOP CLIP.	21072	\$14.00	7 150514

Subject to Protective Order: Williams v. Remington

BARBER - REM DOCSB0010200

MAE00010116