	П
	ᆽ
	7
	XITS
	ä
	5
	Š
	×
	- 22
	Ü
	Œ
	ě
	ب
	10%
_	7
3	- 17
Þ	4
Ð	_
ö	
=	
9	
0	
10	
$\circ$	

		20000000						
1169								
//		****	4 200		REPLACED EXTRACTOR, PLUNGER &			
ĊТ	597	2654663	11-97	M10, M23	SPRING, CHECKED OVER, CLEANED & OILED, REPLACED TRIGGER ASSY & NEW TYPE	20629	\$47.55	
ОН	597	26 <b>5682</b> 3	111-97	SAFETY & TRIGGER WON'T WORK.	EJECTOR, CLEANED, CHECKED AND TEST	21060	\$88.21	
AL	597	2641341	12-97	1/19	ADJUSTED EJECTOR. REPLACED EXTRACTOR, SPRING & PLUNGER	21056	\$22.50	
MN	597	2663762	12-97	M10	AND TEST FIRED. REPLACED EXTRACTOR, SRING &	20017	\$47.95	
CAN	597	2662376	112-97	DOES NOT PULL EMPTY SHELL OUT		20401	\$38.40	
WI	597	2657827	112-97		LATCH. ADJUSTED EJECTOR, REPAIRED BOLT HOLD	20616	\$16.59	
MI	<b>5</b> 97	2666081	101-98	M9, M10 SHELLS WILL NOT EJECT	OPEN SPRING. INSTALLED NEW EJECTOR, EXTRACTOR &	20108	\$42.00	
OR	<b>5</b> 97	2667119	01-98	PROPERLY.	PLUNGER CLEANED AND TESTED.	20023	\$45.18	
FL	597	2664871	101-98	CHANGE OUT TO NEW EJECTOR.	INSTALLED NEW STYLE EJECTOR.	20030	\$17.23	
MN	597	2666719	1 101-98	M5	REPLACED & FIT BROKEN BOLT HANDLE	20017	\$30.57	
СТ	597	2664346	01-98	M9, M10, M23	REPLACED EXTRACTOR PLUNGER SPRING & MAGAZINE, CHECKED OVER, CLEANED &	20629	\$50.08	
NC	597	2653361	01-98	TRIGGER WOULD NOT RESET ITSELF.	REPLACED TRIGGER ASSY.	21102	\$60.23	
W	597	2672166	02-98	M9	FIRED.	21027	<b>\$</b> 36.32	
MD	<b>5</b> 97	2675633	02-98	WON'T FIRE.	REASSEMBLED & STAKED TRIGGER LINK. REINSTALLED PIN THAT HOLDS TRIGGER	20021	\$10.60	
W	597	2674014	02-98	WOULD NOT FIRE.	ASSY TO SEAR AND REINSTALLED SEAR	20616	<b>\$35</b> ,00	
MN	597	2673872	02-98	M23, M28	REPAIRED LINKAGE IN TRIGGER ASSY TO OPERATE SMOOTHLY, ADJUSTED EJECTOR	20017	\$47.27	
CAN	597	2676522	02-98	M9	REPLACED BBL, REPROOFED, REFIT SIGHTS.	268418	\$95.07	
NY	597	2671430	02-98	M10	REPLACED EXTRACTOR, PLUNGER & SPRING, FUNCTION & SAFETY CHECKED AND	21036	\$22.11	
ARG	597	2672215	102-98		REPLACED FRONT SIGHT AND SCREW.	104476	\$60.73	

BARBER - REM DOCSB0010243