

OH	597	A2650483	05-01	CHECK TO SEE IF OKAY.	GROUND EJECTOR FOR BOLT CLEARANCE, INSTALLED NEW TYPE OF EJECTOR,	21060	\$50.25
AL	597	A2650667	05-01	M10	HONED CHAMBER.	21056	\$22.50
AL	597	A2650798	05-01	M10	HONED CHAMBER.	21056	\$22.50
OK	597	A2649728	05-01	M9	INSTALLED NEW STYLE EJECTOR, DISENGAGED ISS SYSTEM, SAFETY & TEST	21047	\$29.95
OK	597	A2650926	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.46
OK	597	A2650822	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95
OK	597	A2650072	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OK	597	A2650530	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.46
OK	597	A2650981	05-01	M9	INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58
OH	597	A2651332	05-01	SHOOTS HIGH.	INSTALLED NEW TYPE EJECTOR, INLET	21060	\$56.75
OH	597	A2651240	05-01	CLIP COMES OUT WITHOUT HITTING THE RELEASE.	STOCK PROPERLY, CLEANED, CHECKED AND INSTALLED NEW TYPE OF EJECTOR.	21060	\$55.18
AL	597	A2650305	05-01	M10	REPLACED MAGAZINE, GROUND EDGE OF	21056	\$22.50
MN	597	A2649771	05-01	M8, M9	POLISHED CHAMBER.	20017	\$44.14
OH	597	A2650170	05-01	NOT ACCURATE.	REPAIRED TRIGGER LINKAGE TO OPERATE FREELY, ADJUSTED EJECTOR TO ENGAGE	21060	\$61.75
NY	597	A2652941	05-01	M145	REPLACED BOLT ASSY, INSTALLED NEW STYLE EJECTOR, CLEANED, CHECKED AND	21177	\$20.00
NY	597	A2650464	05-01	M9	REPLACED BOLT HANDLE, BOLT SPRING & RIVET AND EJECTOR, SAFETY & FUNCTION	21177	\$20.00
NY	597	A2652037	05-01	M134	REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND TESTED.	21177	\$20.00
CT	597	A2651199	05-01	M9, M23, M33	REPLACED MAG BOX, REPLACED EJECTOR, SAFETY & FUNCTION CHECKED AND	20629	\$48.32
SC	597	A2651510	05-01	M33	REPLACED MAGAZINE & EXTRACTOR, CHECKED OVER, CLEANED & OILED, SAFETY	21044	\$18.78