

Photo Captions

- 001 • The new SPL trigger (left) has virtually the same footprint as the original. The only readily seen difference is in the safety lever itself, and the presence of a second, larger inspection hole in the housing.
- 002 • The new trigger retains the same bolt stop/release of the original.
- 003 • When engaged, the new pivoted link trigger system blocks both trigger and sear, but allows the action to be cycled.
- 004 • In the "Fire" position, the blocker is withdrawn, allowing the upper extension of the trigger to move forward, releasing the sear.
- 005 • no caption needed.
- 006 • no caption needed.