BARBER - REM DOCSB0013071

Fails to extract during endurance. Design changed, need to re-do DAT testing and more endurance testing.

Perniciaro to e-mail LE impact of resources to Cahan and Bunting

C:\Program Files:TGDI\CrackerLoaderREM\REMEmail\rawblob\20060107071736A00006192.docPage 8

6/12/2006