

- The team would like to review a new report of the code M129 (fails to extract), by date produced (2003 – ytd) and Date repaired. John L to produce reports before next meeting
- Danny E talked about the new model **700 fluted trigger pins**. The question was raised about using these pins with and without the ISS system. Should we have any concerns? Ken N -Drop test issues? At this time the ISS firing pin assembly is restricted.
- Bob Orf and Steve P advised the team that there is no reason to restrict the new fluted firing pin assembly for parts sales. The new firing pin meets all specifications for standard and ISS assemblies and is interchangeable.
- Steve added that we should send a trigger lock when converting from the ISS to the new fluted assemblies.
- **Model 332** was discussed briefly. The bluing salt problem was discussed, Jerry A advised that the new bleed line was in place and that as of this month August, we all guns with be going through it.

**Notes:**

- **Next meeting will be on September 8<sup>th</sup>, 11:00 am – noon. If you cannot attend our meeting, please let me know as far in advance as possible.**
- **We will follow-up next meeting on 700 accuracy concerns, Model 870 fails to extract, Model 7400 fore-end testing and Model 332 concerns.**

Confidential

Page 3

6/12/2006