

Warning: wait at least one full minute after firing the last round before pouring powder into the bore to allow time for any residual sparks to be extinguished.