

John Trull

---

**From:** Trull, John  
**Sent:** 01/13/2004 08:45:34 AM  
**To:** Waldo, Jonathan W.  
**CC:** Bullis, Gene R.; Allen, Gerald R.; Call, Virginia L.; VanSickle, William C.;  
Brewer, Jim L.; Caudill, Christopher J.; Shoemaker, Christopher D.; Perniciaro, Stephen  
**BCC:**  
**Subject:** RE: 700 BDL Trigger Pull

Steve P. will have the gun tomorrow, but it has to be turned around fast. I tried to adjust the pull down, but something is obviously binding up inside, so I left it alone. Anyhow, you will have it tomorrow.

John C. Trull

Marketing Manager - Firearms Division

Remington Arms Company, Inc.

P.O. Box 700

870 Remington Dr.

Madison, NC 27025-0700

(336) 548-8737 - Phone

(336) 548-7737 - Fax

john.trull@remington.com

www.remington.com

---

**From:** Waldo, Jonathan W.  
**Sent:** Monday, January 12, 2004 6:37 PM  
**To:** Trull, John  
**Cc:** Bullis, Gene R.; Allen, Gerald R.; Call, Virginia L.; VanSickle, William C.; Brewer, Jim L.; Caudill, Christopher J.; Shoemaker, Christopher D.; Perniciaro, Stephen  
**Subject:** RE: 700 BDL Trigger Pull

The "Z" is added onto the receiver at final inspection in the case of a possible "DUP" when the serial number shows it has already been packed. We place the original serial number on "DUP" hold in the warehouse and "Z" the gun in question so as to pack it. It has been a process that has been used for quite a while now and one that I would like to get out of.

We are currently working with John Balio and Mark Courage on a plan to reduce the serial number errors at pack by changing the sequence in which a serial number gets entered, and then re-entered into the system for verification.