BARBER - REM DOCSB0017541

		લ	
Model	788		
Total Units	564,000		
Last date of production	1983		
Non Walker Trigger			
cost per unit waranty cost per unit Labor Benefits Parts Overhead Charge to Firearm Owner Remington Pickup	Avg cost per unit 26.62 11.68 6.43 24.84 48.54 112	Replace i hour \$. 8768 \$	Grind I hour \$ 15.00 \$ - \$ - \$ 24 \$ 39 20 \$ 19.00
Estimated Returns % Estimated Returns - Units		Replace 0.0% -	Grind 1.0% 5,640
Cost		\$ -	\$ 107,160
can	remove small portion of top not replace fire control - cu that fix any parts in firearm	rrently offer trade up p	oricing to model 700 f parts- offer trade up to mode
Notes	, , , , , , , , , , , , , , , , , , , ,		

New Update Program - 2001 Boll Lock Gun

- 1 Clean Jubricate & keep exisiting fire control and cut off tab gun in good working condition
- Firecontrol altered or state of disrepair can not replace fire control Offer trade up pricing to
- 3 Have cleaned, keep bolt lock feature and get a video on safe gun handling
- 4 Find problems customer does not want fixed & sign waiver that gun should not be used in cu