

MODEL
XP-100

DATE OF CALL BACKS

Set. 1992 To Aug. 1994

Set. 1989 To Dec. 1989

Jan. 1987 To Oct. 1988

All SN under 7507984
*Except those with a
Prefix of "A" or "B"

PROBLEMS

Possible miss-cut in stock inletting, the
Pistol may discharge if Dropped on the
Muzzle with the safety off (in the fire
Position)

Return to: Remington
Attn: Dept. XPSC
Ilion, NY 13357

Firing pin head with below specification
Heat treatment. Premature wear may
show in this part which could eventually
cause harder than normal bolt lifting, and
in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.
Attn: Dept. FP
Ilion, NY 13357

the Front guard screw may position
itself in a manner that could promote
Unintentional firing upon release of the
safety or upon closing the bolt.

Return to: Remington Arms Co., Inc.
Attn: Dept. XP
Ilion, NY 13357

Under certain unusual circumstance, the
safety selector and trigger of these
firearms could be manipulated in a way
That could result in accidental discharge.