

MODEL  
XP-100

DATE OF CALL BACKS

Set. 1992 To Aug. 1994

Set. 1989 To Dec. 1989

Jan. 1987 To Oct. 1988

All SN under 7507984  
\*Except those with a  
Prefix of "A" or "B"

PROBLEMS

Possible miss-cut in stock inletting, the  
Pistol may discharge if Dropped on the  
Muzzle with the safety off (in the fire  
Position)

Return to: Remington  
Attn: Dept. XPSC  
Ilion, NY 13357

Firing pin head with below specification  
Heat treatment. Premature wear may  
show in this part which could eventually  
cause harder than normal bolt lifting, and  
in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.  
Attn: Dept. FP  
Ilion, NY 13357

the Front guard screw may position  
itself in a manner that could promote  
Unintentional firing upon release of the  
safety or upon closing the bolt.

Return to: Remington Arms Co., Inc.  
Attn: Dept. XP  
Ilion, NY 13357

Under certain unusual circumstance, the  
safety selector and trigger of these  
firearms could be manipulated in a way  
That could result in accidental discharge.