

**BOLT ACTION CALL BACKS**

**MODEL**  
**XP-100**

**DATE OF CALL BACKS**

**PROBLEMS**

Set. 1992 To Aug. 1994

Possible miss-cut in stock inletting, the Pistol may discharge if dropped on the muzzle with the safety off (in the Fire Position)

Return to: Remington

Attn: Dept. XPSC  
Ilion, NY 13357

Set. 1989 To Dec. 1989

Firing pin head with below specification Heat treatment. Premature wear may show in this part which could eventually cause harder than normal bolt lifting, and in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.

Attn: Dept. FP  
Ilion, NY 13357

Jan. 1987 To Oct. 1988

the Front guard screw may position itself in a manner that could promote un-intentional firing upon release of the safety or upon closing the bolt.

Return to: Remington Arms Co., Inc.

Attn: Dept. XP  
Ilion, NY 13357

All SN under 7507984  
\*Except those with a  
Prefix of "A" or "B"

Under certain unusual circumstance, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.