

M700 Fire Control - Trigger Pull Results

Date		Low					High			Totals	
		<3.5	3.5	3.75	4	4.25	4.5	7	7.25	7.5	>7.5
1/9/2006 2nd	blue fixt.				1	1		6	4	4	12
1/9/2006 2nd	pink fixt.							1	3		1
1/10/2006 1st	blue fixt.				1			17	6	2	11
1/10/2006 1st	pink fixt.				1		7	1			1
1/10/2006 2nd	blue fixt.										
1/10/2006 2nd	pink fixt.										
1/11/2006 1st	blue fixt.										
1/11/2006 1st	pink fixt.										
1/11/2006 2nd	blue fixt.										
1/11/2006 2nd	pink fixt.										
12-Jan	blue fixt.										
	pink fixt.										
	blue fixt.										
	pink fixt.										
13-Jan	blue fixt.										
	pink fixt.										
	blue fixt.										
	pink fixt.										
Week Total -		0	0	0	3	1	7	25	13	6	25

figures on 1/10 are cumulative thru 1 p.m.

17 of 36, blue rejects for testing "hi" on 1/10 were corrected by applying molycoat to the sear safety cam and trigger connector viewing hole in the side of the trigger housing.

8 of 36, blue rejects for testing "hi" on 1/10 had moly coat applied to the sear safety cam and trigger connector viewing hole and fell below the 4 lb. pull limit.

grb 1/10/2006