

Printed on:
~AUTODATE

TEMPERATURE:

MAXIMUM LOAD:

TIME:

QUENCH:

REMARKS: Must Be Clean of Oil and Dirt Before Magna-Flux
Must Be Demagnetized After Inspection 100%
(Good Parts Only)

INSPECT FOR: Cracks Around Hole

HEAT TREAT INSPECTION:

STANDARD PRACTICE NO:

HARDNESS LIMITS:

APPEARANCE OF PARTS:

PROCESS CONTROL INSPECTION RECORD THIS RECORD MUST STAY WITH THE PRODUCTION ORDER AT ALL TIMES		Revision Date: 27-Jun-02	Processed by:
Part No:	Part Name: Trig Con 700 7 700SS 7SS	C/F Rifle	Date: 6/14/2006
Operation No: 50	Operation: Wash, Magneflux, Inspect 100%, Demagnetize		Work Center: