

Bob Orf

From: Orf, Robert J.
Sent: 01/05/2006 07:47:01 PM
To: Kelly, John W.
CC:
BCC:
Subject: RE: Action Log - 700 FC issues

I will check John, but we should only have a select group making these adjustments. If the final assemblers are making adjustments, What screws are they adjusting? Engagement should only be done in the fire control assembly area.

From: Kelly, John W.
Sent: Thu 1/5/2006 6:45 PM
To: Orf, Robert J.
Subject: Re: Action Log - 700 FC issues

It is my understanding that assemblers have been doing this right along. If we send everything back, I believe we will stop processing product, for the most part.

Sent from my BlackBerry Wireless Handheld

-----Original Message-----

From: Orf, Robert J.
To: Perniciaro, Stephen; Kilborne, Carl C.; Kelly, John W.; Call, Virginia L.; Bullis, Gene R.; Truax, Sheldon F.; Mroz, John B.; Bullis, Gene R.; Call, Virginia L.
CC: Bennett, Gary; Paestella, Michael M.; Diliberto, Joseph
Sent: Thu Jan 05 17:56:55 2006
Subject: RE: Action Log - 700 FC issues

I do not agree with having the final assemblers adjusting fire controls for trigger pull. We need to get the other items addressed and should be gathering all of the fire controls that are rejected by the builders and have them re-inspected by the fire control assembly department. If these fire controls are set to the specs and do not meet our criteria for creep etc. they should be turned over to engineering for inspection.

DO NOT HAVE FINAL ASSEMBLERS ADJUSTING FIRE CONTROLS!!!!

Thanks

Bob Orf

From: Perniciaro, Stephen
Sent: Thu 1/5/2006 4:28 PM
To: Orf, Robert J.; Kilborne, Carl C.
Cc: Bennett, Gary
Subject: FW: Action Log - 700 FC issues