

CAL.- 30.06

#3

PROJECT#241095:

[illegible]

Coverpg

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710

Project: 241095

Rifle: C-9

TLW #: TLW0300

Date: 12 / 15 / 00

Inspector: Terrell

Round Level: 500

☒ Measure Headspace Mint. 0.03

☒ Sear Engagement: .0244

☒ Trigger Pull: 1st. 3.75 2nd. 3.5 3rd. 3.75

Ave. 3.66

Check the following areas for signs of unusual wear or breakage:

- ☒ Receiver insert
- ☒ Rear surface of Bolt Lugs
- ☒ Check for "galling" on rear of Bolt Lugs
- ☒ Bolt Plug
- ☒ Bolt Plug Insert "ears" on firing pin assembly
- ☒ Check for loose or missing pins - make note and re-stake if necessary
- ☒ Check plastic inserts for cracks or other damage.
- ☒ Firing Pin Head for Looseness. Loose
- ☒ Check Firing Pin Tip for Looseness.
- ☒ Check Take Down Screws for Movement. Show new position relative to original mark.

 Rear OLC  Middle  Front

Position after re-torque:

 Rear  Middle  Front

☒ Check Diaz Bracket Screw for looseness. _____

☒ Check Bolt Stop SLIGHTLY OVER THE 170V MIN T

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below: _____

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07406