

CAL.- 30.06

#3

PROJECT#241095

[illegible]

Coverpg

6

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

Clean & Inspect Checklist, Series C T&P

Model: 710

Project: 241095

Rifle: C-15

TLW #: TLW0300

Date: 12 / 15 / 00

Inspector: Teste

Round Level: 500

- ☒ Measure Headspace Min +.002
- ☒ Sear Engagement: .0248
- ☒ Trigger Pull: 1st 4.0 2nd 4.5 3rd 4.25 Ave. 4.25

Check the following areas for signs of unusual wear or breakage:

- ☒ Receiver insert
- ☒ Rear surface of Bolt Lugs
- ☒ Check for "galling" on rear of Bolt Lugs
- ☒ Bolt Plug
- ☒ Bolt Plug Insert "ears" on firing pin assembly
- ☒ Check for loose or missing pins - make note and re-stake if necessary
- ☒ Check plastic inserts for cracks or other damage.
- ☒ Firing Pin Head for Looseness.
- ☒ Check Firing Pin Tip for Looseness.
- ☒ Check Take Down Screws for Movement. Show new position relative to original mark.

 ole Rear

 ole Middle

 ole Front

Position after re-torque:

 ole Rear

 ole Middle

 ole Front

- ☒ Check Diaz Bracket Screw for looseness. _____

- ☒ Check Bolt Stop slight anterior movement

Take digital photographs, if appropriate, to record unusual wear, damage or other note-worthy observations. List the digital file name for reference along with any comments below. _____

TLW0300

TESTPLAN_Rev1_C_Series.doc

Remington Confidential

Revision # 1

ET07418