

CAL: 300 WIN MAG

PROJECT # 241314

Logform

Bob Lee

ET1969

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	JHW1303A		
JS/BL	12/22/03	De-Torque Scope Cross Bolt Front 25 in 1b Rear 25 in 1b			
BL	12/22/03	Headspace min. .004			
BL	12/22/03	Proof OK		1	1
BL	12/22/03	Headspace min. .004			
JS/BL	12/22/03	Depth of Front Take down screw hole			
BL	12/23/03	Firing Pin Indents .019-.019-.018 Avg. .0186			
JS	12-29-03	Seal/Trigger Engagement Avg. .0219			
JS	12-29-03	Sear lift .0177			
SW/JS	1-13-04	Charge out Bolt Head			
SW/JS	1-13-04	Headspace Min T.005			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min + .005			
BL	1/15/04	200rd Basic Jack Funct Test Bolt hard to close all ammo magazine hard to take from magazine well.		200	202
SW/BL	1/15/04	Headspace Min + .005			
PR	1-16-04	Shoulder Function x 20 Rds. Bolt difficult to close		20	222
BL/JS	1-19-04	Inspect & Clean See Inspection sheet			

Logform

ET19970

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-1

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: BL

Round Level: 222

☒ Measure Headspace min + .005

☒ Sear Engagement: 1st. .0251 2nd. .0263 3rd. .0269

Ave. .0254 spec. .020" to .025" .0238

☒ Trigger Pull: 1st. 4.720 2nd. 4.626 3rd. 4.472

Ave. 4.606 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Locking lugs show wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: insert has a defect must be in the mold

TLW1303

Remington Confidential

ET19971