

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW 1303A		
JS	12/22/03	De-torque SCOPE	Cross Bolt Front 25 in lb Rear 30 in lb		
BL	12/22/03	Headspace	Min .003		
BL	12/22/03	PROOF	OK	1	1
BL	12/22/03	Headspace	Min .004		
JS/BL	12/22/03	Depth Front Take	Down screw style		
BL	12/22/03	Firing Pin Indents	.020 .020 .020 Avg .020		
JS	12-29-03	Sear/Trigger Engagement	Avg .0275		
JS	12-29-03	Sear lift	.0162		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.006		1	2
SW/JS	1/13/04	Proof Bd			
SW/JS	1/13/04	Headspace after proof	Min +.006		
B Lee	1/15/04	200rd Basic Jack Funct. test	Bolt hard to close Rem PRA300wc/magazine hard to take from magazine well	200	202
SW/BL	1/15/04	Head space	Min +.006		
J.U.	1-16-04	Shoulder Function	20 Rds. Bolt difficult to close	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

6

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-3

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min +.006

☒ Sear Engagement: 1st. .0282 2nd. .0282 3rd. .0282

Ave. .0282 spec. .020" to .025"

☒ Trigger Pull: 1st. 5.290 2nd. 5.420 3rd. 5.543

Ave. 5.418 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary. Top Take down screw loose

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Bolt stop some wear Locking Lugs some wear

☒ Inspect stock for any signs of cracking or other

failure.

☒ Other items of

note: magazine Box protruding, insert has a defect must be in the
mold

TLW1303

Remington Confidential

ET19975