

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Do-Torque SCOPE CROSS Bolt screw	Front 30inL6 Rear 32inL6		
BL	12/22/03	Headspace	min+.002		
BL	12/22/03	Proof	Tight opening Bolt	1	1
BL	12/22/03	Headspace	min+.002		
JS/BL	12/22/03	Length front Take down crew			
BL	12/23/03	Firing Pin Indent.	.021-.023-.021 Avg. .0206		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0272		
JS	12-29-03	Sear lift	.0175		
SW/JS	1-13-04	Charge out Bolt Head			
SW/JS	1-13-04	Headspace Min+.004			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof Min+.004			
SW	1/14/04	200 Rd Basic Jack Function Test		200	202
SW/BL	1/15/04	Headspace Min+.004			
H.D	1-16-04	Shoulder Function test x 20 rds.	slow; FTEX3: Bolt hangs when pulled to the rear; Bolt release goes beyond stopping point.	20	222
JS/BL	1-19-04	Inspect & Clean	see inspection sheet		

Logform

ET19982

Confidential - Subject to Protective Order

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-7

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 1222

- ☒ Measure Headspace min⁺ .004
- ☒ Sear Engagement: 1st .0278 2nd .0278 3rd .0276 Ave. .0279 spec- .020" to .025" BSV Eng
- ☒ Trigger Pull: 1st 4.488 2nd 4.599 3rd 4.387 Ave. 4.457 spec- 4 lb to 5.5 lb. .0245
- ☒ Check Take-Down Screws and Re-tighten if necessary.
- ☒ Inspect extractor & bolt face area.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop some wear
- ☒ Inspect stock for any signs of cracking or other failure.
- ☒ Other items of note: Receiver insert has a defect must be in the mold, magazine box protruding

TLW1303

Remington Confidential

ET19983