

CAL: 300 WIN MAG

PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW100JA		
JS	12/22/03	Detorque - Scope Crosshair Screws	Front 15 Rear 27		
BL	12-22-03	Headspace	Min + .004		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min to .004		
JS/BL	12-23-03	Depth Front Take down Scope hole			
BL	12-23-03	Firing Pin Indent	.020 - .029 - .019 Avg .0193		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0341		
JS	12-29-03	Sear lift	.0162		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min + .005		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min + .005		
SW	1/14/04	200 Rd Basic Jack Function Test		200	202
SW/BL	1/15/04	Headspace	Min + .005		
DM	1-16-04	Shoulder Function test X20 Rds.	Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection sheet		

Logform

— 6 —

ET19986

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-9

TLW #: TLW1303

Date: 01 19 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .005

☒ Sear Engagement: 1st .0323 2nd .0325 3rd .0326

Ave. .0324 spec. .020" to .025"

☒ Trigger Pull: 1st 4.785 2nd 5.001 3rd 4.959

Ave. 4.915 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking Lugs some wear, Bolt stop some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box is protruding, receiver insert has a defect must
be in the mold.

TLW1303

Remington Confidential

ET19987