

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate - Scope Crosshair Shows	Front 30 Rear 30		
BL	12-22-03	Headspace			
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	Min + .021		
JS/BL	12-23-03	Depth Front Take down Scope hole			
BL	12-23-03	Firing Pin Indent	.000 - .022 Avg .0219		
JS	12-29-03	Gear/Trigger Engagement	Avg. .026		
JS	12-29-03	Gear lift	.0163		
SW/JS	1-13-04	Change out B.H. Head			
SW/JS	1-13-04	Headspace Min + .000	Won't close up on Min	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace after proof	Min + .00 (won't close up on Min)		
SW	1/14/04	200 Rd Basic J22k Function Test		200	202
SW/BL	1/15/04	Headspace	Min + .00 (won't close up on Min)		
JS	1-16-04	Shoulder Function Test X 20 Rds.	Shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection Sheet Broken extractor		

Logform

Q

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-10

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS / BL

Round Level: 222

☒ Measure Headspace min +.001

☒ Sear Engagement: 1st. .028 2nd. .026 3rd. .026

Ave. .0268 spec. .020" to .025"

☒ Trigger Pull: 1st. 4.62 2nd. 4.65 3rd. 4.685

Ave. 4.649 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Bolt stop excessive wear, Locking lugs some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine box is protruding, receiver insert has a defect must be in mold.

TLW1303

Remington Confidential

ET19989