

CAL: 300 WIN MAG

PROJECT # 241314

				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detonate Scope Crosshair	Front 25 Rear 30		
BL	12-22-03	Headspace	Min + .005	1	1
BL	12-22-03	Proof	OK		
BL	12-22-03	Headspace	Min + .005		
JS/BL	12-22-03	Depth Front Take down Screw hole			
BL	12-23-03	Firing Pin Indents	.020 - .022 - .020 Avg. .0206		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0298		
JS	12-29-03	Sear lift	.017		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min + .006	1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace after proof	Min + .006		
JS	1-14-04	200 Rd. Basic Jack function test	Bolt hard to close throughout test; Bolt hard to open rds. #181-200, Magazine was bent on front side	200	202
SW	1-15-04	Headspace	Min + .006		
BL	1-16-04	Shoulder Function test	X20 Rds. Shot clean	20	222
JS/BL	1-19-04	Chain & Inspect	See Inspection Sheet		

Logform

ET19996

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-14

TLW #: TLW1303

Date: 01 11 19 19

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min +.006

☒ Sear Engagement: 1st. .0282 2nd. .0269 3rd. .0275

Ave. .0275 spec- .020" to .025"

☒ Trigger Pull: 1st. 4.785 2nd. 4.496 3rd. 5.360

Ave. 4.880 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Locking lugs some wear Bolt stop some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine box is protruding - receiver insert has a
defect must be in the mold.

TLW1303

Remington Confidential

ET19997