

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

			ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	
SW/PR	12/19/03	Out of box inspection	TLW1303A	
JS	12-22-03	Detonate - Scope Crossbolt Screws	Front 17 Rear 25	
BL	12-22-03	Headspace	min +.005	
BL	12-22-03	Proof	OK	1
BL	12-22-03	Headspace	min +.005	1
JS/BL	12-22-03	Depth Front Take down 5 Screw hole		
BL	12-23-03	firing Pin Idents	.020 .021 .021 Avg. .0206	
JS	12-29-03	Sear/Trigger Engagement	Avg. .0004	
JS	12-29-03	Sear Lift	.014	
SW/JS	1-13-04	Change out Bolt Head		
SW/JS	1-13-04	Headspace Min +.005		
SW/JS	1/13/04	Proof Rd		1 2
SW/JS	1/13/04	Headspace After proof Min +.006		
JS	1-15-04	200 Rd Jack Function test - Bolt hard to close on Rds 121-140		200 202
SW	1-15-04	Headspace Min +.006 (All Takedown screws were loose)		
BL	1-16-04	Shoulder Fire Bolt Hard to close		20 222
JS/BL	1-19-04	Clean & Inspect See Inspection Sheet		

Logform

— 44 —

Williams v. Remington

ET20000

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-16

TLW #: TLW1303

Date: 01 1 19 1 04

Inspector: J. BL

Round Level: _____

☒ Measure Headspace min + .005

☒ Sear Engagement: 1st .0291 2nd .0304 3rd .0283

Ave. .0292 spec. .020" to .025" RSD 53F

☒ Trigger Pull: 1st 4.556 2nd 4.485 3rd 4.507

Ave. 4.516 spec- 4 lb. to 5.5 lb. .025

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Bolt face has some wear

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs - Bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20001