

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

				ROUNDS AT START-0	
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	THW 1303A		
JS/BL	12/22/03	De-Torque Scope Cross Bolt Front	25 in 16 Rear 25 in 16		
BL	12/22/03	Head space	min+.004		
BL	12/22/03	PROOF	OK	1	1
BL	12/22/03	Head space	min+.004		
JS/BL	12/22/03	Depth of Front Take down screw hole			
RL	12/23/03	Firing Pin Indents	.018-.019 Avg. .0186		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0217		
JS	12-29-03	Sear lift	.0177		
SW/JS	1-13-04	Charge out Bolt Head			
SW/JS	1-13-04	Head space Min+.005			
SW/JS	1/13/04	PROOF Rd		1	2
SW/JS	1/13/04	Head space after proof	Min+.005		
BL	1/15/04	200rd Basic Jack Funct Test	Bolt hard to close all ammo/magazine hard to take from magazine well.	200	202
SW/RL	1/18/04	Head space	Min+.005		
PR	1-16-04	Shoulder Function	20 Rds. Bolt difficult to close	20	222
BL/JS	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

ET20108

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-1

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: BL

Round Level: 222

☒ Measure Headspace min + .005

☒ Sear Engagement: 1st .025 2nd .026 3rd .0269

Ave. .0261 spec- .020" to .025" SP Set

☒ Trigger Pull: 1st 4.720 2nd 4.626 3rd 4.472

Ave. 4.606 spec- 4 lb to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. Broken extractor

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Locking lugs some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of note: insert has a defect must be in the mold

TLW1303

Remington Confidential

ET20109