

CAL: 300 WIN MAG

PROJECT # 241314

CAL: 300 WIN MAG				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Detonate Scope Cross Bolt	Front 25 in 16 Rear 20 in 16		
BL	12/22/03	Head space	min +.002	1	1
BL	12/22/03	Pront	OK		
BL	12/22/03	Head space	min +.002		
JS/BL	12/22/03	Depth Front Take Down Screw	head		
BL	12/23/03	Firing Pin Indent	would also take crusher holder for Endents		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0293		
JS	12-29-03	Sear Lift	.016		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Head space Min +.005		1	2
SW/JS	1/13/04	Pv005 Rd			
SW/JS	1/13/04	Head space after prev. Min. .005			
BL	1/15/04	200rd Basic Jack front test	Bolt head to close Rem PRA300WC 4FTE/magazine hard to take from magazine well	200	202
SW/BL	1/15/04	Head space	Min +.005		
JK	1-16-04	Shoulder Function	20 Rds. Bolt difficult to close	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

—

ET20110

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-2

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace mint .005

☐ Sear Engagement: 1st. 2nd. 3rd.

Ave. spec- .020" to .025"

☐ Trigger Pull: 1st. 2nd. 3rd.

Ave. spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary. Take down screws loose Top

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Locking lugs & same wear, bolt stop some wear

☐ Inspect stock for any signs of cracking or other failure.

☒ Other items of note: magazine Box protruding, insert has a defect must be in the mold.

Couldn't do engagement or trigger, Mike Kenney took bolts head to ext evaluated

TLW1303

Remington Confidential

ET20111