

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

CALC 000 WIN MARK				ROUNDS	AT START-0
NAME	DATE	TEST ACTIVITY	COMMENTS	RDS. FIRED	TOTAL RDS.
SW/BR	12/19/03	Out of box Inspection	THW1303A		
JS	12-22-03	Deterque - Scope Crosshairs	Front 25 Range 25		
BL	12-22-03	Headspace	min +.005	1	1
BL	12-22-03	Proof	OK		
BL	12-22-03	Headspace	min +.005		
JS/BL	12-22-03	Depth Front Take down	Screw hole		
BL	12-23-03	Fitting Pin Incident	.012 - 1019 Aug 1014		
JS	12-29-03	Seer/Trigger Engagement	Arg. .0281		
JS	12-29-03	Seer lift	.0112		
SW/JS	1/13/04	Change out Bolt Head			
SW/JS	1/13/04	Headspace Min +.007		1	2
SW/JS	1/13/04	Proof Rd			
SW/JS	1/13/04	Headspace After proof	Min +.007		
JS	1-15-04	200 Rd. Jack Function test	Bolt difficult to close on. Rds. 81-100; 121-140	200	202
SW	1-15-04	Headspace Min +.007	(Front Takedown screw missing, center was loose)		
BL	1-16-04	Shoulder Fire	Bolt hard to close	20	222
JS/BL	1-20-04	Clean & inspect	See Inspection sheet		

Logform

50

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-20

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .007

☒ Sear Engagement: 1st .0246 2nd .025 3rd .0248

Ave. .0248 spec- .020" to .025" 83

☒ Trigger Pull: 1st 4.222 2nd 4.777 3rd 4.759

Ave. 4.586 spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive

wear: Bolt stop excessive wear, locking lugs some wear

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20147