

**CAL: 300 WIN MAG**

PROJECT # 241314

| NAME  | DATE     | TEST ACTIVITY                    | COMMENTS                                                                   | ROUNDS AT START-0 |            |
|-------|----------|----------------------------------|----------------------------------------------------------------------------|-------------------|------------|
|       |          |                                  |                                                                            | RDS. FIRED        | TOTAL RDS. |
| SW/PA | 12/19/03 | Out of box Inspection            | TLW1303A                                                                   |                   |            |
| JS    | 12/22/03 | De-torque Scope                  | Cross Bolt Screws Front 30 Rear 30                                         |                   |            |
| BL    |          | Head space                       | min +.005                                                                  |                   |            |
| BL    |          | Proof                            | Tighten scope Emblem on bottom of stock fell off                           | 1                 | 1          |
| BL    | 12/22/03 | Head space                       | min +.005                                                                  |                   |            |
| JS/BL | 12/22/03 | Depth Front Take down Screw hole |                                                                            |                   |            |
| BL    | 12/23/03 | Firing Pin Indents               | .022-.022-.022 Avg .022                                                    |                   |            |
| JS    | 12-29-03 | Sear/Trigger Engagement          | Avg. .0259                                                                 |                   |            |
| JS    | 12-29-03 | Sear lift                        | .0178                                                                      |                   |            |
| SW/JS | 1/13/04  | Change out bolt head             |                                                                            |                   |            |
| SW/JS | 1/13/04  | Head space                       | Min +.006                                                                  |                   |            |
| SW/JW | 1/13/04  | Proof Rd                         |                                                                            | 1                 | 2          |
| SW/JW | 1/13/04  | Head space after proof           | Min +.007                                                                  |                   |            |
| Blue  | 1/15/03  | 2nd JAIL Funct test              | magazine Box hard to take from magazine well / 11 FTE<br>Bolt hard to lock | 200               | 202        |
| SW    | 1-15-03  | Head space                       | Min +.007 (Front Take down screw loose)                                    |                   |            |
| BL    | 1-16-04  | Shoulder Fire                    | magazine came out / Bolt stop not functioning properly<br>1 FTE            | 20                | 222        |
| JS/BL | 1-20-04  | Clean & Inspect                  | See Inspection sheet                                                       |                   |            |

100

ET20151

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-23

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS/BL

Round Level: 222

☒ Measure Headspace min + .001

☒ Sear Engagement: 1<sup>st</sup> .0231 2<sup>nd</sup> .0233 3<sup>rd</sup> .0231

Ave. .0231 spec .020" to .025" **83**

☒ Trigger Pull: 1<sup>st</sup> 5.042 2<sup>nd</sup> 5.177 3<sup>rd</sup> 5.070

Ave. 5.096 spec 4 lb to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop worn

☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: magazine Box protruding

TLW1303

Remington Confidential

ET20152