

CAL: 300 WIN MAG

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW/BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW/BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .005		
SW/BL	2/16/2004	PROOF ROUND		1	1
SW/BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	INDENTS			
SW/BL	2/17/04	SEAL LIFT	SEE DATA SHEET		
SW/BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW/BL	2/17/04	TRIGGER PULL			
BL	2/19/04	200rd JACK Funct.		200	201
JS	2/27/04	500rd Ext. Endur. Test		500	701
BL	3/9/04	Clean/Inspection	See Inspection Sheet		

Logform

Qu

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-17

TLW #: TLW1303

Date: 3 19 104

Inspector: BL

Round Level: 701

- ☒ Measure Headspace min: .006
- ☒ Inspect Take Down Screws for loosening. Top screw 1/4 turn - Center screw 1/2 turn 83
- ☒ Sear Engagement: 1st. .0319 2nd. .0320 3rd. .0317 Ave. .0316 spec- .025" to .030"
- ☒ Reset Sear Engagement if Required: 1st. .0271 2nd. .0273 3rd. .0277 Ave. .0273
- ☒ Trigger Pull: 1st. 4.822 2nd. 4.968 3rd. 4.812 Ave. 4.867 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave.
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, locking lugs some sign of wear
- ☒ Inspect stock for any signs of cracking or other failure: Cracked stock at center screw hole

☐ Other items of
note: _____

TLW1216

Remington Confidential

ET21101