

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL AND PILOT TEST 1.1

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK		
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .004		
SW / BL	2/16/2004	PROOF ROUND		1	1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .005		
SW/JW/BL	2/16/04	INDENTS			
SW/BL	2/17/04	SEAL LIFT	SEE DATA SHEET		
SW/BL	2/17/04	ENGAGEMENT	↓ ↓ ↓		
SW/BL	2/17/04	TRIGGER PULL			
JK	2/19/04	200 Rd JACK Hunt.		200	201
BL/JW	3/1/04	500 Rd EXT. Endur Test		500	201
JS/BL	3/2/04	Clean / Inspection	see inspection sheet		

Logform

Q

ET21125

Confidential - Subject to Protective Order

Williams v. Remington

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Model: 710 Magnum

Project: 241314

Rifle: A-29

TLW #: TLW1303

Date: 3 12 104

Inspector: J. Sims / B. Lee

Round Level: 701

- ☐ Measure Headspace min+.004.
- ☐ Inspect Take Down Screws for loosening. Center take down screw was 1/8 of a turn
- ☐ Sear Engagement: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____ spec. .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☐ Trigger Pull: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____ spec. 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Cam surface, Locking Lugs, bolt stop show some wear, Cam surface worn excessively, bolt difficult to open after firing.
- ☐ Inspect stock for any signs of cracking or other failure. stock cracked at the center take down screw

☐ Other items of

note:

Remington Confidential

Confidential - Subject to Protective Order
Williams v. Remington