

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 9 18 104

Inspector: SN

Round Level: 2281

☒ Measure Headspace Min +.006

☒ Sear Engagement: 1st .0350 2nd .0356 3rd .0353 Ave. .0353 spec. .020" to .025" 83

☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____

☒ Trigger Pull: 1st 4.539 2nd 4.561 3rd 4.582 Ave. 4.561 spec. 4 lb. to 5.5 lb.

☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____

☐ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Locking lugs normal wear

☒ Inspect stock for any signs of cracking or other

failure. Cracked (See Todd Cook) 45° anterior crack is only on shooter's right side .0225"± and nearly closed. This is better than the old material on 30-06. PASS JDC

☐ Other items of

note: _____

TLW1216

Remington Confidential

ET23050