

## REMINGTON MODEL 710 Trial and Pilot SERIES C PRELIMINARY MEASUREMENTS

				George one					
				(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	FIRING	PIN HEAD TO SEA	AR.		ISS FUNCTION TE
FIRECONTROL INSPECTION TLW0300AU			FIRING PIN ASSEMBLY INSPECTION		ENGAGEMENT, TLW0300N		BOLT STOP &	BOLT STOP & RELEASE FUNCTION TEST	
TRIGGER RETURN	GAP	SEAR MOVEMENT	CHECK FOR	TIGHTNESS	measure	ment method	TLW0300O, GI	UNS C-11 TO C-20	GUNS C-11 TO C-20
out of stock @ 20x		in stock by feel	TIP	PHEAD TO	produces a dimension range		STOP FUNCTI	ON RELEASE DETENT	
OK	NONE	FREE	ОК	OK 📆	*35.	.058069	}		1
OK	NONE	FREE	OK	OK ""		.061072			
OK	NONE	FREE	OK	LOOSE	18673, 533,65 (18675, 355 (1867)	.062073	}		
OK	NONE	FREE	OK	OK. 音樂學	) (295)	.070081	1		i e
OK	NONE	FREE	OK	LOOSE	2100 PM	.066077			
OK	NONE	FREE	OK	OK	100	.064075			
OK	NONE	FREE	OK	OK OK	{	<b>3</b> 064075	1		
OK	NONE	FREE	OK	ok 🖏		<del></del>			
OK	NONE	FREE	OK	LOOSE	barrais	.068079			
OK	NONE	FREE	OK	OK		066, 077			1
OK	NONE	FREE	OK	LOOSE	- 100 (M)	.067 <b>-07</b> 8	ОК	GOOD	PASS
OK	NONE	FREE	ОК	OK	Table 1	070081	ОК	GOOD	PASS
OK	NONE	FREE	OK	OK		065076	OK	GCOD	PASS
OK	NONE	FREE	ОК	OK	732	.064075	OK	GOOD	PASS
ok	NONE	FREE	ОК	OK	10 Mg	.06607%	OK	GCOD	PASS
OK	NONE	FREE	OK	LOOSE		_:: <u>.::</u> 1964075	ОК	POOR, LOOSE	PASS
OK	NONE	FREE	OK	OK	1,43	069-:080	ОК	GOOD	PASS
OK	NONE	FREE	OK	LOOSE		.06 <del>5</del> .076	ОК	POOR, LOOSE	PASS
OK	NONE	FREE	OK	OK		<b>.0</b> 66077	ОК	GOOD	PASS
OK	NONE	FREE	ок	OK		066-077	OK	GOOD	PASS
OK	NONE	FREE	OK	LOOSE		روايدي 065076.	<u> </u>		
OK	NONE	FREE	ОК	OK		.062073	· ii		
OK	NONE	FREE	OK	OK	ļ	.068079	<b>1</b> 0		1
ok	NONE	FREE	ОК	LOOSE		.070081	_ n :\$}:		1
OK	NONE	FREE	ОК	OK	1	.062073	- 1000 m		
OK	NONE	FREE	ОК	LOOSE	ł	.064075			
OK	NONE	FREE	OK	LOOSE	ŀ	.062073			
OK	NONE	FREE	OK	LOOSE	ļ	.069080	A A A A A A A A A A A A A A A A A A A		
OK	NONE	FREE	OK	OK	1	.064075			
OK	NONE	FREE	ОК	LOOSE	1	.067078			