

CONFIDENTIAL

Remington Arms Company Inc.
RESEARCH & DEVELOPMENT TECHNICAL CENTER
315 WEST RING ROAD
ELIZABETHTOWN, KY 42701

3.1.1.2 **TLW0300B – Packaging Audit –**

(T&P Series "A") - performed by Marketing as specified by the test plan.

The following is from an e-mail message sent to concerned parties by John C. Trull, Product Manager – Firearms. John performed a marketing audit on the first shipment of trial and pilot rifles (T&P, "A") shipped from Mayfield to the Elizabethtown site. This letter describes the results of that audit.

Packaging

Overall, packaging looked good. There were no cartons damaged outside of a few minor tears that did not penetrate through the corrugated container. All guns were secure inside of the package and did not appear to have shifted. With the exception of three guns packaged without ISS keys, all required contents were present.

Stock

Overall appearance of the 710 stock was good. No marking to speak of was noticed. In my opinion, I saw nothing that would inhibit our ability to proceed with the production of the gun, however below are some comments which hopefully can be addressed with the implementation of a new mold at some point next year.

- On approximately half of the guns, a noticeable gap existed along the left-hand side of the barrel. In contrast, the right hand side of the barrel on the same guns showed very little or no gap. In the more extreme cases, when viewed from the muzzle, the barrel appeared off center in it's bedding.
- On the same guns, a more noticeable gap appeared on the right rear corner of the receiver/stock mate (by the safety lever) than was visible on the left. With the both of these gap issues, it was almost as if the barreled action was not mounted straight into the stock.
- On nearly all guns, the safety lever dug slightly into the stock when placed in the "fire" position. Mike Keeney said that the only good way to address this would be to build a shelf into the stock when a new mold was constructed.
- One stock was observed with excessive "sink" on the left-hand side. A "not to exceed" sample was identified which Mayfield will measure in order to obtain maximum acceptance criteria.

Bolt Camming/Bolt Translation

Force required to cam the bolt into battery was noted to be tight but acceptable on essentially all guns. My opinion is that if we can take measures to reduce this on future production, we should do so. The issue raised by all was how to consistently and accurately measure bolt camming force. No consensus was reached on how to do so. I feel strongly that we should explore developing a means to test this criterion on the Model 710.

Jan. '01 Trial & Pilot Test - Remington M/710 Centerfire Rifle;
R & D Technical Center Project No. 241039; TLW 0300
File: E:\Test Reports\Firearms Tests\710 T&P_3006\M710_T&P_REPORT_JAN01_Rev0.doc

Page 14

CONFIDENTIAL

ELI-0-00206 1/27/01

Subject to Protective Order - Williams v. Remington

BARBER - 5.30.06R0001879

ETE00001878