

**REMINGTON RECOGNIZED CAUSES OF
M700 MALFUNCTIONS AND MISFIRES**

- 1. OIL OR DIRT IN FIRE CONTROL**
- 2. ADJUSTMENT OF ENGAGEMENT,
OVERTRAVEL OR POUNDAGE
SCREWS BY CUSTOMER**
- 3. COLD WEATHER WHEN COMBINED
WITH OIL IN FIRE CONTROL**
- 4. TRIGGER PULLED WHILE SAFETY IN
INTERMEDIATE POSITION AND
THEN SAFETY RELEASED -
"TRICKING"**

