

DON'T SAY IT-WRITE IT

To E. LARSON - BDPT.

Date 9-30-80

From J.P. LINDE - ILION

RECEIVED

OCT 1 1980

E. G. LARSON

In regard to our telephone conversation, September 29, this is an example of what happens when the Trigger Assembly is oiled too much.

JPL:js
Attach.

"SAFETY RULES ARE PERFECT TOOLS"

R2509391

John Daniel
Sportsmen's Equipment Company

"DAN DWYER"
GUNS and FISHING TACKLE
915 W. WASHINGTON STREET
SAN DIEGO, CALIFORNIA 92103
(714) 296-1501



Remington Arms Company, Inc

Ilion, N.Y. 13357

ATT: Mr. Vic Rostokar

Dear Vic - While I'm working on it, and it is fresh in my mind; I had better write this. I have meant to before this but something else always interferes.

This is one of several Trigger difficulties of this same kind in recent months.

The customer brought this Mod 700 to me complaining that blamed thing fired when he released the safety. It only happened when the outside temperature was very cold. He had been hunting in Colorado at high altitude.

When I took it apart, I found it badly gummed up with WD-40 (confirmed by questioning him).

Nothing wrong with the Trigger except his own tampering, the gummy WD-40 and the cold weather.

He had pulled the Trigger when the safety was on, the gummy WD-40 held it retracted and when the safety was switched off the inevitable happened:

I've had several of these same cases in recent months. All Triggers were gummed up with rust preventatives.

Please inform your engineering people.

Sincerely

Dan Dwyer, Sr.

Daniel I. Dwyer, Sr.

Remington recommended Gausma.

To B. G. Larson

10/1/70

Earl

Note Benson. This

Comment on

gunny preserve time

RECEIVED

OCT 2 1961

L. G. LARSON

From J. H. Chisnall

REMINGTON ARMS COMPANY, INC.
**Trigger Assembly
 Special Replacement Program**

(A) GUNSMITH

Name Sportsmen's Equip
 Street 915 W. Washington St
 City, State, Zip San Diego CA 92103
 Telephone (Area Code)
 Control No. 1519196
 (For Rem. Use Only)

GUN OWNER

Name Robert Cole
 Street 2925 Pioneer Way
 City, State, Zip San Diego CA 92035
 Telephone 764-461-1415
 (Area Code)
 Control No. (For Rem. Use Only)

(B) FIREARMS INFORMATION

Model (Check One)

- ☒ 1. Rem 600
☐ 2. Rem 660
☐ 3. Mohawk 600
☐ 4. XP-100

Caliber (Check One)

- ☐ 1. 222 Rem.
☐ 2. 6mm Rem.
☐ 3. 243 Win.
☐ 4. 308 Win.
☐ 5. 6.5mm Rem. Mag.

Caliber (Check One)

- ☒ 6. 350 Rem. Mag.
☐ 7. 35 Rem.
☐ 8. 223 Rem.
☐ 9. 221 Rem. "Fireball"
☐ 10. Rechambered

Serial No.

39783

(C) MODIFICATION INFORMATION

Method Gun Received From Owner:

(Check One)

- ☒ Hand Delivered
☐ UPS
☐ U.S. Mail
☐ Other _____
 (Specify)

Month Day Year

Date Gun Received From Owner 9 23 80Estimated Completion Date 9 23 80

(D) INVOICE DATA

This gun was very badly jammed up through use of a gunny preservative. A warning should be put out against the use of such. There are several brands.
I can't expect the gun to rise properly in such a condition.

Date Work Completed

9 23 80

Gunsmith Signature

Date

Charges: Modification Charge \$5.00
 Transportation
 Other (Detail Below):
 cleaning & finish Total \$ 15.00

INVOICE COPY

(to be mailed for payment upon completion of work)

REV. 4-78

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington



cc: R. B. Sperling
C. B. Workman
J. H. Linde

October 3, 1980

To: J. P. Glas
From: E. G. Larson
Subject: Gummed Triggers

Please see the attached from John Linde and Jack Chisnall, relative to lubricants gumming up trigger mechanism, resulting in a safety problem.

One of these relates to WD40, but I have also heard that the protective coating we use (Steel Guard) will also gum up in time, and freeze trigger components.

My question is, should this be investigated more fully, and do we properly warn in our instruction manuals?

E. G. Larson
E. G. Larson

EGL:lb

R2509390